

# LIFESPAN<sup>®</sup>

---

## SOLID SELECT

REAL WOOD. REDEFINED.

Siding, Trim & Mouldings

## INSTALLATION TECHNICAL SERVICE BULLETIN

1. We recommended top coating Lifespan with paint that has a Light Reflective Value (LRV) greater than 40. Using colors with a lower LRV will cause much higher temperatures on the sidewall and could, in some cases, raise the grain of the wood and or cause the primer/topcoat to fail. This is not a manufacturing defect.
2. If the surface is broken when nailing Lifespan, make sure to putty and fill nail holes to ensure the surface is sealed. Not filling nail holes may result in moisture uptake at the nail penetration, which could lead to raised grain.